Town of Lancaster Tree Warden NOTICE OF PUBLIC HEARING

In accordance with Massachusetts General Laws (MGL), Chapter 87, Public Shade Tree Law, Section 3 (Cutting of Public Shade Trees; Hearing; Damages), the Town of Lancaster Tree Warden will hold a Public Hearing regarding an application from National Grid to remove or prune public shade trees on **Monday, May 20, 2019 at 7:00 p.m.** in the Town Hall Auditorium, 695 Main Street, Lancaster, MA. Any person interested or wishing to be heard on this matter should appear at the time and place designated.

The program included a tree-by-tree hazard assessment of public and private trees, along the main three-phase lines which serve the community. The work is recommended to remove hazard trees and prune for additional clearance to reduce tree outage problems affecting large numbers of customers served by these main lines. National Grid's arborists have identified forty- seven (47) town trees for removal along town roads, and six (6) town trees for pruning. Town trees located within the public way that are designated for removal have been posted with a notice of public hearing in the field. Trees designated for pruning have been marked with a small blue ribbon.

The roads with town trees affected by the program are Main Street, Langen Road, Goss Lane, Narrow Lane, Center Bridge and Seven Bridge Roads.

A complete list of town trees designated for removal or pruning including information about the location, size and species of the affected trees and the reason for work proposed, is available weekdays from the Town Hall, Library and Highway Department during normal business hours.

Kevin Bartlett Tree Warden

Town of Lancaster (Town-owned Trees)

Town of La							}	1		
IE Hazard	Tree Mitiga	tion Program								annual and the second second second second
lazard Tre	e Removal	List			***************************************	_			And the state of t	*- Table to the contract of
Circuit # 22	5W1								11 CARP STEADS A SALES AND A S	Shiphus marrows regan distance and arthur files and an are so
			1	-		-				
Number	Site ID	Street Name	House #	Location	Pole #	Dia.	Species	# Stem	Defect Condition	Manual Property and Property an
			1.				1	1		Work Proposi
1_	RH05	Main St	2120		213-212	30	Ash		EAB susceptible; weight over lines	
2	RH06A	Main St	2069	AF	210-209	37	Sugar Maple	1	Dead; Tree warden request	Remove
									Dead leads; >40% crown decline;	Remove
3	RH08	Main St	1958		204-203	29	Ash		EAB susceptible	P3
4	RH10	Main St	Lot		186-185	15	Ash	1	EAB susceptible	Remove
5	RH10	Main St	Lot		186-185	12	Sugar Maple		Base decay	Remove
	Dulde					I Day	- William Thomas		Trunk decay @ line height; base	Remove
6 / 7	RH10	Main St	Lot		184-183	13	Red Maple		wound	D
	RH10	Main St	Lot		176-175	10	Sugar Maple	2	Bank erosion	Remove
							Vol apropried to the same		Root decay: -50% crown decline:	Remove
8	RH11	Main St	Lot		176-175	20	Ash		bank erosion	D
9	RH12A	Langen Rd	Lot		73-72.5	25	Red Maple		Back side cavity	Remove
1								-	And the last of th	Remove
			1					1	Crown decline; many rotting wounds	
1				1					from previous crown failures; pine	
40	D1140								growing in codominant union; large	
10	RH13	Langen Rd	156	AF	72-71	35	Red Maple		cavities in center lead near union	Remove
11	RH14	Langen Rd	97		71-70	11	Red Maple		Base decay; multiple cavities	
12	RH14	Langen Rd	97		71-70	21	W. Pine	1	Codominant trunks; PS request	Remove Remove
13	RH15	Langen Rd	290	AF	67-66	- 36	Red Maple		Decaying cavity @ union	Remove
		1.		1			Contracting to page 1 or and paragraphics		Severe base, trunk and crown	Kemove
14	RH15	Langen Rd	290	AF	67-66	38	Ash		decay	Remove
15	RH16	Langen Rd	245		65-64	16	Ash		Base wound: EAB susceptible	Remove
									Many crown breaks; included bark	Veluose
									codom; some girdling roots; owner	
16	RH17	Langen Rd	275		63-62	44	Sugar Maple	i	request	Remove
							Manager W. Manager Street, Springer		Lean; severe crown decline; small	veluove
43					İ				cavity @ eye level w/decay; EAB	
17	RH18	Langen Rd	Lot	- AF	58-57	19	Ash		susceptible	Remove
40							-		Base decay; lean; fungal fruiting	remove
18	RH18	Langen Rd	Lot	AF	56-55	24	Red Maple		bodies @ base; girdling roots	Remove
								***	Fungal fruiting bodies at seam with	Lamove
				1					dead leader/ base cavity with decay/	
19	RH27	Langen Rd	456		51-50	38	Norway Maple		50% crown decline	Remove
00	Dilloc						manufacture of the second section of the section of the second section of the second section of the second section of the section of the second section of the sec		Account of the state of the sta	Launna -
20	RH28	Langen Rd	474		50-49	25	Ash		May crown failures/ EAB susceptible	Remove

Town of Lancaster (Town-owned Trees)

own of La								~11-	PONSTANCE OF A PROPERTY OF THE	pakana akamen akamen ang ang ang ang ang ang ang ang ang an
		tion Program		1						
4-4-	Removal I	_ist								I see the second
ircuit # 22	5W1								The state of the s	the second secon
									Annual Manager & London Co.	defendance i memorial community. Appropriate in colors
Number	Site ID	Street Name	House #	Location	Pole #	Dia.	Species	# Stem	Defect Condition	Work Proposed
1 1		1 .	1.	f I)	Crown decline/ lean/ gypsy moth	
21	RH30	Langen Rd	471	AF	46-45	23	White Oak		susceptible/ overhang	Remove
22	RH31	Langen Rd	554		46-45	27	Norway Maple		Severe trunk decay	Remove
23	RH31	Langen Rd	554	AP	45	35	Norway Maple		Trunk wounds with decay	Remove
24	RH33	Langen Rd	Lot		38-37	45	Red Oak		Overhang, weight reduction trim	Trlm
		A STATE OF THE STA		1						The state of the s
25	RH33	Langen Rd	Lot		33-32	19	Hickory		Cavity at base/ some crown failures	Remove
1									Galis/ fungal fruiting bodies on	The second second second second second second second
26	RH33	Langen Rd	Lot	AP	28	15	Cherry		trunk/ crown decline	Remove
									Multiple cavities/ crown decline/	A series of Appendix Series (Series Series)
27	RH33	Langen Rd	Lot		28-27	29	Norway Maple		weight over lines	Remove
28	RH33	Langen Rd	Lot		28-27	14	Red Maple	1	Trunk decay	Remove
29	RH33	Langen Rd	Lot		28-27	19	Norway Maple		Over hang/ base decay	Remove
30	RH33	Langen Rd	Lot		28-27	25	Norway Maple		Over hang/ base decay	Remove
31	RH33	Langen Rd	Lot		27-26	19	Cherry	1	Left lead severe crown decline	Remove
32	RH36	Goss Ln	Lot	AP !	6	37	Red Maple		Trim 5" limb over lines, see photo	Trim
33	PJ01	Narrow Ln	30	AP	6	14	Sugar Maple		Dead	Remove
34	PJ01	Narrow Ln	30	AP	6	19	Sugar Maple		Dead	Remove
35	PJ01	Narrow Ln	30	AP	6	32	Sugar Maple		Dead	Remove
36	PJ01	Narrow Ln	30		6-5	27	Sugar Maple		Dead	Remove
37	PJ01	Narrow Ln	30		4-3	16	Sugar Maple		Dead leads/ crown decline	Remove
38	PJ05	Main St	971		126-125	37	Red Maple	<u> </u>	Broken crown/ dead leads/ cavities	Remove
39	PJ05	Main St	971		125-124	27	Red Maple		Crown decline 80%	Remove
40	PJ05	Main St	971	-	104-103	24	Red Maple		Crown decline 80%	Remove
41	PJ05	Main St	971	T	104-103	27	Red Maple		Crown decline 80%/ dead leads	Remove
		TO ANTI-	44.			-		1	Dead leads/ crown decay: Tree	THE PARTY OF THE P
42	PJ05A	Main St	976	AF	110-109	37	Sugar Maple		warden request	Remove
engryddrafys 7s yddiddiodddos (s		And the second s			demonth o large appropriate handles are a second				Severe crown decline/ EAB	
43	RH41	Main St	47 Center Bridge Rd		70-66	.17	Ash		susceptible	Remove
44	RH41	Main St	47 Center Bridge Rd	1	70-66	16	Hickory		Base decay	Remove
45	RH42	Main St	lot	1	56-55	30	Pine		40% crown decline	Remove
46	RH49	Main St	307	AP	30	29	Sugar Maple		Trim 5 and 6" branches over lines back to trunk	Trim
47	RH49	Main St	307		30-29	24	Sugar Maple	1	Severe crown decline	Remove

2 of 3

Town of Lancaster (Town-owned Trees)

nationalgrid

own of Lar										
		tion Program				1			The second secon	and the state of the place that the second section is a first of the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the second section in the second section is a first or the section is a first or th
iazard Tree		_ist							The state of the s	el al Megalayaman seguintendo deplarento de de 1110
Circuit # 22	SW1.									amen'n' respectable a fighting a lister of the standard pages, where you
Number	Site ID	Street Name	House #	Location	Pole #	Dia.	Species	# Stem	Defect Condition	Work Proposed
48	RH50	Center Bridge Road	lot	AP	2	47	Pagoda		Back side base cavity and seam; dead limb at line height; branches over wires; remove to trunk 11" branch growing over lines also side dead wood trim	Trim
49	RH51	Center Bridge Road	124		10-11	25	Catalpa		Trim all branches on right side of left lead around secondary height	Trim
50	RH51	Center Bridge Road	124		10-11	.29	Catalpa	·	Hollow center; proximity	Remove
51	RH52	Center Bridge Road	157	AF I	13-14	27	Ash		Severe decay at base	COMMISSION OF THE PERSON OF THE BUILDINGS OF THE PERSONNELS OF THE
52	RH55	Center Bridge Road	435		25-26	68	Sycamore		Trim dead wood over lines	Remove
53	RH58	Seven Bridge Road	lot		6-7	7	Sugar Maple		Base decay	Trim Remove
			~***						Total Removals:	47
				-		-			Total Trims:	6
										e dae, Africanggyga, darett umd y gift - ytg se b. seb.est. 13. yg. 1945 - Hannes Berlin - y gant - se berlin se berlin se gant - se berlin se berlin se berlin se berlin se berlin se gant - se berlin se
										t tight management states and a stight state of the state